



FIG. 1



**FIG. 2**



SCANNING EXPOSURE DIRECTION



09964648-092801

FIG. 3




FIG. 4





FIG. 5A



WHEN EVALUATION VALUE IS IN STATIC EXPOSURE AREA,  
FORCIBLY CORRECT IT TO SCANNING EXPOSURE AREA

FIG. 5B




FIG. 6




FIG. 7






FIG. 8A




FIG. 8B






FIG. 9



09964648-09201

FIG. 10



0964648-09801

FIG. 11

URL

TROUBLE DB INPUT SCREEN

DATE OF OCCURRENCE  ~ 1404

MODEL  ~ 1401

CASE NAME  ~ 1403

DEVICE  ~ 1402

EMERGENCY LEVEL  ~ 1405

SYMPTOM  ~ 1406


REMEDY  ~ 1407

PROGRESS  ~ 1408

1410 1411 1412

[LINK TO RESULT LIST DATABASE](#) [SOFTWARE LIBRARY](#) [OPERATION GUIDE](#)

T08260-84949660

**FIG. 12**

SEMICONDUCTOR DEVICE MANUFACTURING FLOW

0954648-092801

FIG. 13

